

Laurila Surveying

Professional Land Surveyors

H. David Laurila, P.S.

15333 Shortle Rd., Sterling, OH 44276-9615

www.laurilasurveying.com

hdlaurila@laurilasurveying.com

Situated in the Township of Congress, County of Wayne and State of Ohio and being part of the Southeast Quarter of Section 11, T-21 north, R-14 west and being bounded and described as follows:

Commencing at 3/4" rebar found at the southeast corner of the Southeast Quarter of Section 11; thence S88°42'34"W, 822.47' along the centerline of Sterling Road, C.R. 59, a 60' right way and the Section Line to the **TRUE POINT OF BEGINNING**;

- 1.) thence S88°42'34"W, 576.24' along the centerline of said Sterling Road and the Section Line to a point;
- 2.) thence N03°19'30"W, 373.92' to a 5/8" rebar with a "Laurila 7663" cap set, passing through a 1" pipe found at a distance of 25.00';
- 3.) thence N88°42'34"E, 589.50' to a 5/8" rebar with a "Laurila 7663" cap set;
- 4.) thence S01°17'30"E, 373.69' to the **TRUE POINT OF BEGINNING**, passing through a 5/8" rebar with an orange "Laurila #7663" cap set at a distance of 351.80'.

The above described parcel contains 5.000 acres according to Wayne County Tax Map Office Survey Book WW, Page 030 as surveyed by H. David Laurila, P.S. 7663 of Laurila Surveying on March 9, 2018.

The Basis of Bearing is Grid North per ODOT Vrs.



OK MM 3/15/18

3-09-2018

