

Laurila Surveying

Professional Land Surveyors

H. David Laurila, P.S.
15333 Shortle Rd., Sterling, OH 44276-9615
Phone 330-819-4415
www.laurilasurveying.com

Situated in the Township of Milton, County of Wayne and State of Ohio and being part of the Southwest Quarter of Section 4, T-18 north, R-12 West and being bounded and described as follows:

BEGINNING at a "Mag" nail found in a bridge deck at the southwest corner of the said Southwest Quarter of Section 4;

1.) thence $N00^{\circ}49'51''W$, 481.67' along the Section Line to a 5/8" rebar with a "Laurila 7663" cap found;

2.) thence $N89^{\circ}14'11''E$, 247.11' to a 5/8" rebar with a "Laurila 7663" cap set;

3.) thence $S03^{\circ}34'10''E$, 482.25' to a point on Zigler Road, T.R. 43, a 40' right of way, passing through a 5/8" rebar with an orange "Laurila #7663" cap set at a distance of 444.55';

4.) thence $S89^{\circ}14'11''W$, 270.15' along the centerline of Zigler Road and the Section Line to the **TRUE POINT OF BEGINNING**.

The above described parcel contains 2.860 acres according to Wayne County Tax Map Office Survey Book WW, Page 291 as surveyed by H. David Laurila, P.S. 7663 of Laurila Surveying on October 25, 2018.

The Basis of Bearings are GRID North per ODOT vrs.



OK MM 10/26/18